KE2060 KEYES voltage sensor module

Parameters:

Working voltage：0V-25V DC
Colour: Red
Size: 39x22x12mm.



PINOUT Instruction:



Sample Code:

```
int analogpin=0;     // Define analogpin as analog port 0
int val,val5;       //Define variables val,val5
int val2=0;      //Define variables val2
int val3=0;     //Define variables val3
int val4=0;    //Define variables val4
void setup()
{
   Serial.begin(9600);     //Set baud rate of 9600
}
void loop()
{
   int val,val5;
   float val1;
   val=analogRead(analogpin);     //Read the value of the analog port and assign it to the variable val
   val1=val/3.9;
   val5=(int)val1;
   val3=val5/100;
   val2=(val5%100)/10;
   val4=val5%10;
   Serial.print("$CLEAR\r\n");      //clear the screen
   Serial.print("$GO 1 1\r\n");
   Serial.print("$PRINT Voltage:\r\n");
   Serial.print("$GO 1 9\r\n");
   Serial.print("$PRINT ");
Serial.print(val3);        //The serial port prints the value of the variable val3
Serial.print(val2);      //The serial port prints the value of the variable val2
   Serial.print(".");              //The serial port prints out a point"."
   Serial.print(val4);         //The serial port prints the value of the variable val4
   Serial.println("V");          //The serial port prints out capital " V"
   delay(100);      //delay 0.1 second
}
```

Result:

Done as the above wiring, compile and upload the code, powered-on, then open the serial monitor, it will print out the detected voltage value shown below.