



## Notice of Designation of Maintenance and Obsolete Thick-Film Hybrid ICs (Affected products: Products listed below)

Thank you for using SANYO semiconductor products. We will be introducing the technology mentioned in the title as described below. Please take note of this introduction.

### Memorandum

#### Affected Products:

STK405-030	STK407-070	STK408-090E
STK405-030A	STK407-070E	STK4102MK2
STK405-050	STK407-090	STK4112MK2
STK405-050A	STK407-090E	STK4122MK2
STK405-070	STK407-100	STK4132MK2
STK405-070A	STK407-100E	STK4142MK2
STK405-090	STK407-110	STK4152MK2
STK405-090A	STK407-110E	STK4162MK2
STK405-100	STK407-120	STK4171X
STK405-100A	STK407-120E	STK4172MK2
STK405-110	STK407-240	STK4182MK2
STK405-110A	STK407-250	STK4192MK2
STK405-120	STK407-270	STK4201MK2
STK407-040	STK407-290	STK4211MK2
STK407-040E	STK408-040E	STK4221MK2
STK407-050	STK408-050E	STK4231MK2
STK407-050E	STK408-070E	STK4241MK2

#### Reason for Designation:

To optimize the product lineup.

#### Date of Implementation:

September 2001.

Contact your SANYO sales representative if you have any questions or require more detailed information regarding this change.